



NATO SUPPORT AND PROCUREMENT AGENCY
AGENCE OTAN DE SOUTIEN ET D'ACQUISITION

NATO UNCLASSIFIED

REQUEST FOR PROPOSAL (RFP) N°:
BLV24014 /LC-CC-6001003217

INTERNET VENDOR

L-

(Please refer to this number in all further correspondence)

Contact Point

Bernadette LOPEZ VILLACIS

Tel: 3063 4300

Fax: 3063 4300

Offer Closing date: 27 May 2024

Offer Validity : 30 Dec 2024

Vendor No: RFPWEB

Fax No : 30634300

Table of contents:

RFP Bidding Instructions

Terms and Conditions

Annex A Technical Proposal

Annex B Price Proposal

Matrix BLV24014 1

Matrix BLV24014 2

List of Services

Yours faithfully,

Bernadette LOPEZ VILLACIS

Buyer LA-MMC

NATO UNCLASSIFIED

List of Services

Service Order N°: 10131989
Part Number: 2117804-3
Customer Document N°: DSPAD431890001
S/N: DSPAD43189FAKE1

Line	Service No	Description	Unit of Issue	Qty
10	1161326	INSPECTION 1660013121722 CONTROLLER,AIR PRESSURE,AIRCRAFT CABIN TASK 1 - FIRM-FIXED INSPECTION COST/B.E.R. COST: In accordance with Part 1, Task 1 of the draft contract Inspection cost for the repair process. Firm Fixed unit price: (currency) TAT: Calendar Days	PU	1
20	1161172	REPAIR 1660013121722 CONTROLLER,AIR PRESSURE,AIRCRAFT CABIN TASK 2 - REPAIR WORK - FIRM-FIXED LABOR REPAIR COST (without the inspection cost): In accordance with Part 1, Task 2 of the draft contract UNDER ROUTINE PROCESS Firm fixed unit price: (currency) TAT Routine: ... Calendar DAYS (TAT for the repair includes the TAT for the inspection)	PU	1

Statement of work:

Unit has to be inspected and repaired in accordance with applicable Technical Documentation, T.O.s, OEM Publications, MIL Standards and Specifications to bring it back to an acceptable operational condition.

The contractor has to perform corrosion/surface treatment as necessary and technical investigation as required.

The final inspection and test release as well as packing and packaging will be performed as per applicable documentation.

Following documentation will be provided with the unit:

A "Release to service" certificate shall be issued by the contractor as follows: (template ANNEX II release to service certificate attached).

For civil parts: EASA "Form One" or FAA Form 8130-3 for American contractors.

For military parts: Certificate of Release to Service

NATO UNCLASSIFIED

Maintenance Release Serviceable TAGs "Material" (Yellow Card)

A report describing the work, which have been done, and a detailed test certificate describing the tests, which have been passed.

Contractor should not use any spare parts containing asbestos. If this is the case NSPA approval is required.

END USER: SPAF
 END ITEM: CN-235

Quality assurance requirements:

This contract shall meet the AQAP 2131 requirements (NATO Quality Assurance Requirements for Final Inspection and Test). These requirements also apply to all sub-contractors involved in this contract.

GQA HEADER:

Government Quality Assurance is not required for this contract.
 The Contractor must provide a Certificate of Conformity (CoC). Template to be used is to be found in AQAP2070.
 In case the contractor is not the manufacturer, the contractor shall provide a copy of the COC received from the manufacturer.

Service Order N°: 10131987
Part Number: 2117804-3
Customer Document N°: DSPAD431890002
S/N: DSPAD43189FAKE2

Line	Service No	Description	Unit of Issue	Qty
10	1161326	INSPECTION 1660013121722 CONTROLLER,AIR PRESSURE,AIRCRAFT CABIN TASK 1 - FIRM-FIXED INSPECTION COST/B.E.R. COST: In accordance with Part 1, Task 1 of the draft contract Inspection cost for the repair process. Firm Fixed unit price: (currency) TAT: Calendar Days	PU	1
20	1161172	REPAIR 1660013121722 CONTROLLER,AIR PRESSURE,AIRCRAFT CABIN TASK 2 - REPAIR WORK - FIRM-FIXED LABOR REPAIR COST (without the inspection cost): In accordance with Part 1, Task 2 of the draft contract	PU	1

NATO UNCLASSIFIED

UNDER ROUTINE PROCESS

Firm fixed unit price: (currency)

TAT Routine: ... Calendar DAYS (TAT for the repair includes the TAT for the inspection)

Statement of work:

Unit has to be inspected and repaired in accordance with applicable Technical Documentation, T.O.s, OEM Publications, MIL Standards and Specifications to bring it back to an acceptable operational condition.

The contractor has to perform corrosion/surface treatment as necessary and technical investigation as required.

The final inspection and test release as well as packing and packaging will be performed as per applicable documentation.

Following documentation will be provided with the unit:

A "Release to service" certificate shall be issued by the contractor as follows: (template ANNEX II release to service certificate attached).

For civil parts: EASA "Form One" or FAA Form 8130-3 for American contractors.

For military parts: Certificate of Release to Service
Maintenance Release Serviceable TAGs "Material" (Yellow Card)

A report describing the work, which have been done, and a detailed test certificate describing the tests, which have been passed.

Contractor should not use any spare parts containing asbestos. If this is the case NSPA approval is required.

END USER: SPAF
END ITEM: CN-235

Quality assurance requirements:

This contract shall meet the AQAP 2131 requirements (NATO Quality Assurance Requirements for Final Inspection and Test). These requirements also apply to all sub-contractors involved in this contract.

GQA HEADER:

Government Quality Assurance is not required for this contract.
The Contractor must provide a Certificate of Conformity (CoC). Template to be used is to be found in AQAP2070.
In case the contractor is not the manufacturer, the contractor shall provide a copy of the COC received from the manufacturer.

NATO UNCLASSIFIED

Service Order N°: 10132474
Part Number: 115-239 ,
Customer Document N°: DSPAD431840001
S/N: DSPAD43184FAKE1

Line	Service No	Description	Unit of Issue	Qty
10	1205545	INSPECTION 6625013082688 AMMETER TASK 1 - FIRM-FIXED INSPECTION COST/B.E.R. COST: In accordance with Part 1, Task 1 of the draft contract Inspection cost for the repair process. Firm Fixed unit price: (currency) TAT: Calendar Days	PU	1
20	1205291	Repair of 6625013082688 AMMETER TASK 2 - REPAIR WORK - FIRM-FIXED LABOR REPAIR COST (without the inspection cost): In accordance with Part 1, Task 2 of the draft contract UNDER ROUTINE PROCESS Firm fixed unit price: (currency) TAT Routine: ... Calendar DAYS (TAT for the repair includes the TAT for the inspection)	PU	1

Statement of work:

Unit has to be inspected and repaired in accordance with applicable Technical Documentation, T.O.s, OEM Publications, MIL Standards and Specifications to bring it back to an acceptable operational condition.

The contractor has to perform corrosion/surface treatment as necessary and technical investigation as required.

The final inspection and test release as well as packing and packaging will be performed as per applicable documentation.

Following documentation will be provided with the unit:

A "Release to service" certificate shall be issued by the contractor as follows:
(template ANNEX II release to service certificate attached).

For civil parts: EASA "Form One" or FAA Form 8130-3 for American contractors.

For military parts: Certificate of Release to Service
Maintenance Release Serviceable TAGs "Material" (Yellow Card)

NATO UNCLASSIFIED

A report describing the work, which have been done, and a detailed test certificate describing the tests, which have been passed.

Contractor should not use any spare parts containing asbestos. If this is the case NSPA approval is required.

END USER: SPAF
 END ITEM: CN-235

Quality assurance requirements:

This contract shall meet the AQAP 2131 requirements (NATO Quality Assurance Requirements for Final Inspection and Test). These requirements also apply to all sub-contractors involved in this contract.

GQA HEADER:

Government Quality Assurance is not required for this contract.
 The Contractor must provide a Certificate of Conformity (CoC). Template to be used is to be found in AQAP2070.
 In case the contractor is not the manufacturer, the contractor shall provide a copy of the COC received from the manufacturer.

Service Order N°: 10132473
Part Number: 115-239 ,
Customer Document N°: DSPAD431840002
S/N: DSPAD43184FAKE2

Line	Service No	Description	Unit of Issue	Qty
10	1205545	INSPECTION 6625013082688 AMMETER TASK 1 - FIRM-FIXED INSPECTION COST/B.E.R. COST: In accordance with Part 1, Task 1 of the draft contract Inspection cost for the repair process. Firm Fixed unit price: (currency) TAT: Calendar Days	PU	1
20	1205291	Repair of 6625013082688 AMMETER TASK 2 - REPAIR WORK - FIRM-FIXED LABOR REPAIR COST (without the inspection cost): In accordance with Part 1, Task 2 of the draft contract UNDER ROUTINE PROCESS	PU	1

NATO UNCLASSIFIED

Firm fixed unit price: (currency)

TAT Routine: ... Calendar DAYS (TAT for the repair includes the TAT for the inspection)

Statement of work:

Unit has to be inspected and repaired in accordance with applicable Technical Documentation, T.O.s, OEM Publications, MIL Standards and Specifications to bring it back to an acceptable operational condition.

The contractor has to perform corrosion/surface treatment as necessary and technical investigation as required.

The final inspection and test release as well as packing and packaging will be performed as per applicable documentation.

Following documentation will be provided with the unit:

A "Release to service" certificate shall be issued by the contractor as follows: (template ANNEX II release to service certificate attached).

For civil parts: EASA "Form One" or FAA Form 8130-3 for American contractors.

For military parts: Certificate of Release to Service
Maintenance Release Serviceable TAGs "Material" (Yellow Card)

A report describing the work, which have been done, and a detailed test certificate describing the tests, which have been passed.

Contractor should not use any spare parts containing asbestos. If this is the case NSPA approval is required.

END USER: SPAF
END ITEM: CN-235

Quality assurance requirements:

This contract shall meet the AQAP 2131 requirements (NATO Quality Assurance Requirements for Final Inspection and Test). These requirements also apply to all sub-contractors involved in this contract.

GQA HEADER:

Government Quality Assurance is not required for this contract.
The Contractor must provide a Certificate of Conformity (CoC). Template to be used is to be found in AQAP2070.
In case the contractor is not the manufacturer, the contractor shall provide a copy of the COC received from the manufacturer.