



NSPA

AGENCE OTAN DE SOUTIEN ET D'ACQUISITION
NATO SUPPORT AND PROCUREMENT AGENCY

List of Services

Table of contents:

RFP BIDDING INSTRUCTIONS
Terms and Conditions
RFP Response Form
Annex A Technical Proposal
Annex B Price Proposal
List of Services



NSPA

AGENCE OTAN DE SOUTIEN ET D'ACQUISITION NATO SUPPORT AND PROCUREMENT AGENCY

List of Services

Service Order N°: 10117621
 Part Number: 4344EA03
 Customer Document N°: DPTAA492840001
 S/N: 1924

Line	Service No	Description	Unit of Issue	Qty
10	1040089	INSPECTION 1680006151335 ACTUATOR,MECHANICAL,AIRCRAFT	PU	1

Item to be inspected.
 Nomenclature: ACTUATOR,MECHANICAL
 NSN : 1680006151335
 P/N : 4344EA03
 S/N : 1924
 Cage code : 63665,78062

TASK 1 - B.E.R. COST

(The overhaul inspection is included in the overhaul cost below)

The fee of line 10 Task 1 "FF Inspection cost" will only be charged if the overhaul work is not performed.

In accordance with Part 1, Task 1 of the draft purchase order.

20	1021151	OVERHAUL 1680006151335 ACTUATOR,MECHANICAL,AIRCRAFT	PU	1
----	---------	--	----	---

Item to be overhauled
 Nomenclature: ACTUATOR,MECHANICAL
 NSN : 1680006151335
 P/N : 4344EA03
 S/N : 1924
 Cage code : 63665,78062

TASK 2- OVERHAUL WORK - FIRM-FIXED COST (with the overhaul inspection cost included):

In accordance with Part 1, Task 2 of the draft purchase order

UNDER ROUTINE PROCESS

Firm Fixed unit price: (currency)

TAT Routine: Calendar Days

Mandatory replacement parts included in the overhaul price:

*** MANDATORY. To be completed in Annex A - Technical Proposal***



NSPA

AGENCE OTAN DE SOUTIEN ET D'ACQUISITION NATO SUPPORT AND PROCUREMENT AGENCY

Statement of work:

Unit has to be inspected and overhauled in accordance with applicable Technical Documentation, T.O.s, OEM Publications, MIL Standards and Specifications to bring it back to an acceptable operational condition.

The final inspection and test release as well as packing will be performed as per applicable documentation.

Following documentation will be provided with the unit:

A "Release to service" certificate shall be issued by the contractor as follows:

For civil parts: EASA "Form One" or FAA Form 8130-3 for American contractors.

For military parts: Certificate of Release to Service.

Maintenance Release Serviceable TAGs "Material" (Yellow Card)

A report describing the work which have been done and a detailed test certificate describing the tests which have been passed.

Contractor should not use any spare parts containing asbestos. If this is the case, NSPA approval is required.

Quality assurance requirements:

This contract shall meet the AQAP 2131 requirements (NATO Quality Assurance Requirements for Final Inspection). These requirements also apply to all sub-contractors involved in this contract.

GQA HEADER:

Government Quality Assurance is not required for this contract.

The Contractor must provide a Certificate of Conformity (CoC). Template to be used is to be found in AQAP2070.

In case the contractor is not the manufacturer, the contractor shall provide a copy of the COC received from the manufacturer.

Service Order N°: 10117622
Part Number: 4344EA-3
Customer Document N°: DPTAA492840002
S/N: 2619

Line	Service No	Description	Unit of Issue	Qty
10	1110828	3040014142019 ACTUATOR,MECHANICAL,LINEAR	PU	1

Item to be inspected.

Nomenclature: ACTUATOR,MECHANICAL,NONAIRCRAFT

NSN : 3040014142019

P/N : 4344EA-3

S/N : 2619

Cage code :63665,78062

TASK 1 - B.E.R. COST

(The overhaul inspection is included in the overhaul cost below)



NSPA

AGENCE OTAN DE SOUTIEN ET D'ACQUISITION
NATO SUPPORT AND PROCUREMENT AGENCY

The fee of line 10 Task 1 "FF Inspection cost" will only be charged if the overhaul work is not performed.

In accordance with Part 1, Task 1 of the draft purchase order.

20 1110827 3040014142019 *PU* 1
ACTUATOR,MECHANICAL,LINEAR

Item to be overhauled.

Nomenclature: ACTUATOR,MECHANICAL,NONAIRCRAFT

NSN : 3040014142019

P/N : 4344EA-3

S/N : 2619

Cage code :63665,78062

TASK 2- OVERHAUL WORK - FIRM-FIXED COST (with the overhaul inspection cost included):

In accordance with Part 1, Task 2 of the draft purchase order

UNDER ROUTINE PROCESS

Firm Fixed unit price: (currency)

TAT Routine: Calendar Days

Mandatory replacement parts included in the overhaul price:

*** MANDATORY. To be completed in Annex A - Technical Proposal***

Statement of work:

Unit has to be inspected and overhauled in accordance with applicable Technical Documentation, T.O.s, OEM Publications, MIL Standards and Specifications to bring it back to an acceptable operational condition.

The final inspection and test release as well as packing will be performed as per applicable documentation.

Following documentation will be provided with the unit:

A "Release to service" certificate shall be issued by the contractor as follows:

For civil parts: EASA "Form One" or FAA Form 8130-3 for American contractors.

For military parts: Certificate of Release to Service.

Maintenance Release Serviceable TAGs "Material" (Yellow Card)

A report describing the work which have been done and a detailed test certificate describing the tests which have been passed.

Contractor should not use any spare parts containing asbestos. If this is the case, NSPA approval is required.



**AGENCE OTAN DE SOUTIEN ET D'ACQUISITION
NATO SUPPORT AND PROCUREMENT AGENCY**

Quality assurance requirements:

This contract shall meet the AQAP 2131 requirements (NATO Quality Assurance Requirements for Final Inspection). These requirements also apply to all sub-contractors involved in this contract.

GQA HEADER:

Government Quality Assurance is not required for this contract. The Contractor must provide a Certificate of Conformity (CoC). Template to be used is to be found in AQAP2070. In case the contractor is not the manufacturer, the contractor shall provide a copy of the COC received from the manufacturer.

Service Order N°: 10117620
Part Number: 374461-5
Customer Document N°: DPTAA492840003
S/N: FA62870048

Line	Service No	Description	Unit of Issue	Qty
10	1040039	1650007849693 SERVOMECHANISM, HYDRAULIC/PNEUMATIC	PU	1

Item to be inspected.
Nomenclature: SERVOMECHANISM, HYDRAULIC/PNEUMATIC, AIRCR
NSN : 1650007849693
P/N : 374461-5
S/N : FA62870048
Cage code : 98897

TASK 1 - B.E.R. COST

(The overhaul inspection is included in the overhaul cost below)

The fee of line 10 Task 1 "FF Inspection cost" will only be charged if the overhaul work is not performed.

In accordance with Part 1, Task 1 of the draft purchase order.

20	1021281	1650007849693 SERVOMECHANISM, HYDRAULIC/PNEUMATIC	PU	1
----	---------	--	----	---

Item to be overhauled.
Nomenclature: SERVOMECHANISM, HYDRAULIC/PNEUMATIC, AIRCR
NSN : 1650007849693
P/N : 374461-5
S/N : FA62870048
Cage code : 98897

TASK 2- OVERHAUL WORK - FIRM-FIXED COST (with the overhaul inspection cost included):

In accordance with Part 1, Task 2 of the draft purchase order



NSPA

AGENCE OTAN DE SOUTIEN ET D'ACQUISITION NATO SUPPORT AND PROCUREMENT AGENCY

UNDER ROUTINE PROCESS

Firm Fixed unit price: (currency)

TAT Routine: Calendar Days

Mandatory replacement parts included in the overhaul price:

*** MANDATORY. To be completed in Annex A - Technical Proposal***

Statement of work:

Unit has to be inspected and repaired overhauled ation, T.O.s, OEM Publications, MIL Standards and Specifications to bring it back to an acceptable operational condition.

The final inspection and test release as well as packing will be performed as per applicable documentation.

Following documentation will be provided with the unit:

A "Release to service" certificate shall be issued by the contractor as follows:

For civil parts: EASA "Form One" or FAA Form 8130-3 for American contractors.

For military parts: Certificate of Release to Service.

Maintenance Release Serviceable TAGs "Material" (Yellow Card)

A report describing the work which have been done and a detailed test certificate describing the tests which have been passed.

Contractor should not use any spare parts containing asbestos. If this is the case, NSPA approval is required.

Quality assurance requirements:

This contract shall meet the AQAP 2131 requirements (NATO Quality Assurance Requirements for Final Inspection). These requirements also apply to all sub-contractors involved in this contract.

GQA HEADER:

Government Quality Assurance is not required for this contract.

The Contractor must provide a Certificate of Conformity (CoC). Template to be used is to be found in AQAP2070.

In case the contractor is not the manufacturer, the contractor shall provide a copy of the COC received from the manufacturer.